

Printable measuring strip — print at 100%, cut and tape together



Wrap around the knuckles (excluding thumb); read the inch mark where the strip overlaps.